Bridge 814/P-40-0509: S Howell Avenue over UPRR
Impact Damage Photos

West Elevation (file photo for reference)

Overall View of damage at Span 2.

Span 2 damage. Note utility connections on Diaphragm.

View along inside edge of Girder 1.

View along outside edge of Girder 1.

View along flange of Girder 2.



View of Girder 2 fractured web.