

**ADDENDUM NO. 1**

This Addendum consists of the following **CHANGES TO THE BID DOCUMENTS FOR OFFICIAL NOTICE 93-1-2016:**

1. **Section 01010, SUMMARY OF WORK, PART 1 – SCOPE OF THE CONTRACT, 1.01 WORK COVERED IN THE CONTRACT DOCUMENTS, Coagulation Basin #4 Flocculator Upgrades, A:**

REMOVE      “8. Perform a “dry interior idler shaft sprocket bearing sleeve assembly inspection of the longitudinal and cross sludge collector system in Sedimentation Basin #4. The work shall include the thorough inspection of all 20 lower cornershaft hub assemblies (10 influent and 10 effluent) of the sedimentation basin. Inspect each assembly (bearing sleeve body, sprocket halves, clamping bands, etc.) for signs of damage/wear, and recommend measures (adjustment/repair/replacement) for extending useful life of the entire sludge collector system.”

INSERT      “8. Perform a “dry interior idler shaft sprocket bearing sleeve assembly inspection of the longitudinal and cross sludge collector system in Sedimentation Basin #4. The work shall include the thorough inspection of all 24 lower cornershaft hub assemblies (12 influent and 12 effluent) of the sedimentation basin. Inspect each assembly (bearing sleeve body, sprocket halves, clamping bands, etc.) for signs of damage/wear, and recommend measures (adjustment/repair/replacement) for extending useful life of the entire sludge collector system.”

**END OF ADDENDUM NO. 1**